

SCOPE OF WORK **(PROVIDED BY GUSD)**

SCOPE:

- **Repair concrete foundation wall in cafetorium at Verdugo woodlands elementary school.**
- **Windows on second and first floor to have all old glazing putty removed and disposed**
- **Metal frames to be treated for rust and corrosion prior to new glazing around windows in affected areas.**
- **Rebar in damaged wall to be cut out back to clean rebar new rebar must be installed anchored or doweled**
- **Concrete to be repaired must be clean of any debris before new application**
- **Ceramic tile on top of wall under affected windows also to be replaced to match existing**
- **Exterior wall under window to be chipped out to expose damage and repair**
- **Interior wall after concrete repair to have wood paneling repaired to match existing**
- **Contractor to accommodate interior floor protection as well as exterior barriers to work area**